



REPORT OF THE TECHNICAL DELEGATES

From: The Technical Delegates

Report N° 04

To: The Stewards of the Meeting

Date: 13/12/2025 **Time:** 11h09

QUALIFYING

Controls were carried out after the Qualifying:

LMP2 - 3 cars	LMP3 - 3 cars	GT3 - 3 cars
Car weight fuel onboard <i>Poids voiture carburant à bord</i>	Car weight fuel onboard <i>Poids voiture carburant à bord</i>	Minimum ground clearance <i>Garde au sol</i>
Diffuser height <i>Hauteur diffuseur</i>	Diffuser height <i>Hauteur diffuseur</i>	BOP Measures - Weight/WD <i>Mesures BOP - Poids/Repart</i>
Skid block thickness <i>Epaisseur planche</i>	Skid block thickness <i>Epaisseur planche</i>	Car weight fuel onboard <i>Poids voiture carburant à bord</i>
Splitter height <i>Hauteur splitter</i>	Splitter height <i>Hauteur splitter</i>	Diffuser height <i>Hauteur diffuseur</i>
Head rest anti-start switch function <i>Head rest fonctionnalité capteur anti-démarrage</i>	extinguisher <i>extincteur</i>	External neutral switch function <i>Fonctionnement bouton neutral externe</i>
Tyre check <i>Contrôle pneumatiques</i>	Head rest anti-start switch function <i>Head rest fonctionnalité capteur anti-démarrage</i>	extinguisher <i>extincteur</i>
Tape on the bodywork <i>Adhésif sur la carrosserie</i>	Tyre check <i>Contrôle pneumatiques</i>	Data check <i>Check data</i>
Driver safety equipment <i>Equipement de sécurité pilote</i>	Tape on the bodywork <i>Adhésif sur la carrosserie</i>	Tyre check <i>Contrôle pneumatiques</i>
Data check <i>Check data</i>	Driver safety equipment <i>Equipement de sécurité pilote</i>	Driver safety equipment <i>Equipement de sécurité pilote</i>
Visual inspection <i>Inspection visuelle</i>	Data check <i>Check data</i>	Visual inspection <i>Inspection visuelle</i>
	Visual inspection <i>Inspection visuelle</i>	

Car #77: The Neutral Button is not working (See Technical Report 02).

Car #43 : The box of the auxiliary battery is missing (See Technical Report 03).

Remi SUDRE
Technical Delegate

Jérôme Marchetti
Technical Delegate